



Sales • Servicing • Mechanical Repairs
Training • Inspections & Testing to Loler Standards

Next Test **16 /01/2019**
Date:

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

RECORD NO. AL0 2490 CUSTOMERS ORDER NO. Verbal DATE THIS RECORD WAS MADE: 16 07 2018

Name & Address of employer for whom the Examination was made:
Safety Platforms Ltd
Unit V4
Carlinghow Mills
501 Bradford Road Batley WF17 8LN

Address of premises at which the examination was made:
Same Safety Platforms Ltd

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998 (SI 2307)

Serial No	Make/Type/Description of Equipment	Date of Make (if known)	S.W.L.	First examination after new location (if known)	Installed correctly	Interval or reason for examination 6m 12m/ WSE or after occurrence	Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if any) if none state 'NONE'	If defect is a danger to persons by what date requirements to remedy defect?	Is the equipment safe to operate?	Where examination including testing. Particular of any tests Proof Load Applied	Last exam date (if known)
1	Of test Piece Telescopic Guard Rail Comprising Of 2 Upright Posts with Welded Base Plates And 2 Telescopic Tube Rails Fixed With Latch Pins Each End Fixed to a Wooden Floor with 8 x Screws Universal Anti Loose Post Arrangement	2018	60Kg Pull Force Applied	Yes	6M					Pull Test Side Ways 60Kg Held For 15 Minutes All Sections Returned To Original Alignment	

E.C. DECLARATION OF CONFORMITY HELD ON FILE

Name of the person making this report: R Ashton Name of person authenticating this report: R Ashton

Qualification of Inspector: CTA Signature: 